


# HD WIPE SAMPLING

## USP <800> states the following:

Environmental wipe sampling for HD surface residue should be performed routinely (e.g., initially as a benchmark and at least every 6 months, or more often as needed, to verify containment).



## SOME RECOMMENDED AREAS to be sampled:

- » Front grille within the C-PEC
- » Cart beside the C-PEC
- » Passthrough
- » Floor in front of the C-PEC
- » Armrest of a patient treatment chair

Monitor and track contamination levels over time with the online platform provided by



Groups of drugs		Limit of detection	
		ng / sample area (ng / 225 cm <sup>2</sup> )	universal unit (ng / cm <sup>2</sup> )
Group 1F	fluorouracil	2	0.009
Group 1M	methotrexate	1	0.004
Group 2	cytarabine	2.5	0.011
	dacarbazine	0.5	0.002
	DOXOrubicin	10	0.044
	epirubicin	10	0.044
	gemcitabine	0.5	0.002
	melphalan	1	0.004
Group 3	cyclophosphamide	0.5	0.002
	DOCEtaxel	30	0.133
	etoposide	2	0.009
	ifosfamide	0.5	0.002
	irinotecan	2	0.009
	methotrexate	1	0.004
	PAcLitaxel	10	0.044
	PEMEtrexed	2	0.009
	topotecan	1	0.004
	vinBLASStine	10	0.044
vinCRISStine	10	0.044	
Group 4	Platins: (CISplatin, oxaliplatin, CARBOplatin)	0.5	0.002
Group 5	Includes all HDs listed above	Refer to the LOD of each HD above	Refer to the LOD of each HD above

## WHAT are the objectives?



**CONTRIBUTE**  
to the assessment of safe practices in the workplace.



**EVALUATE**  
potential HD exposure to staff (pharmacy, nursing, other personnel)



**VALIDATE**  
the effectiveness of decontamination procedures.



**ASSESS**  
the level of compliance of current procedures.

## PRICING

Select the group and multiply the price by the number of swabs needed

Group 1 **Contact us for pricing**

Group 2, 3 or 4 **Contact us for pricing**

Group 5 **Contact us for pricing**

Sampling Kit **INCLUDED FOR FREE**

**Unlock exclusive savings with a subscription**

**CONTACT US TO LEARN MORE**

[www.quess360.com](http://www.quess360.com) [contact@quess360.com](mailto:contact@quess360.com)

1-877-822-5051